



CARFAX® Vehicle History Report™

US \$39.99

An independent company established in 1986

Vehicle Information:

2014 TOYOTA TUNDRA CREWMAX LIMITED

VIN: 5TFHW5F11EX361900

CREW PICKUP

5.7L V8 F DOHC 32V

FLEX FUEL

REAR WHEEL DRIVE W/ 4X4

[Standard Equipment](#) | [Safety Options](#)

CARFAX Report Provided By:

Wheel Kinetics, LLC

1909 W Gardner Ln

Tucson, AZ 85705

(800) 860-0194

www.wheelkinetics.com



No accidents reported to CARFAX



No damage reported to CARFAX



CARFAX 1-Owner vehicle



At least 1 open recall



7 Service history records



117,649 Last reported odometer reading



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 2/8/19 at 2:57:53 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Owner 1

Year purchased

2014

Type of owner

Personal

Estimated length of ownership

4 yrs. 5 mo.

Owned in the following states/provinces

Arizona

Estimated miles driven per year

26,376/yr

Last reported odometer reading

117,649



Title History

CARFAX guarantees the information in this section

Owner 1

[Salvage](#) | [Junk](#) | [Rebuilt](#) | [Fire](#) | [Flood](#) | [Hail](#) | [Lemon](#)

Guaranteed
No Problem

[Not Actual Mileage](#) | [Exceeds Mechanical Limits](#)

Guaranteed
No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [Register](#) | [View Terms](#) | [View Certificate](#)



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.




No Issues Reported

Structural Damage


No structural damage reported to CARFAX.

No Issues Reported

No Issues

Airbag Deployment No airbag deployment reported to CARFAX.	 Reported
Odometer Check No indication of an odometer rollback.	 No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	 No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Toyota dealer near you to schedule an appointment.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Detailed History Glossary

Owner 1	Date:	Mileage:	Source:	Comments:
Purchased: 2014 Type: Personal Where: Arizona Est. miles/year: 26,376/yr Est. length owned: 5/23/14 - 11/6/18 (4 yrs. 5 mo.)	01/20/2014		NICB	Vehicle manufactured and shipped to Arizona
	01/28/2014		Right Toyota Scottsdale, AZ 480-778-2200 righttoyota.com	Vehicle offered for sale
	04/26/2014		Hatch Toyota Show Low, AZ 928-537-5755 hatchtoyota.com	Vehicle offered for sale
	05/12/2014	14	Hatch Toyota Show Low, AZ 928-537-5755 hatchtoyota.com	Pre-delivery inspection completed
	05/23/2014	19	Hatch Toyota Show Low, AZ 928-537-5755 hatchtoyota.com	Vehicle sold
	05/23/2014		Arizona Motor Vehicle Dept. Flagstaff, AZ	Registration issued or renewed Title or registration issued First owner reported Titled or registered as personal vehicle
	06/12/2014		Arizona Motor Vehicle Dept. Chinle, AZ Title #0U07014163106	Registration issued or renewed Title or registration issued Loan or lien reported
	08/26/2014	9,145	Hatch Toyota Show Low, AZ 928-537-5755 hatchtoyota.com	10,000 mile service performed Oil and filter changed Tires rotated Floor mat(s) checked
	09/11/2014		Toyota Motor Sales, USA, Inc.	Manufacturer Safety recall issued NHTSA #14V556 Recall #E0Z SAFETY RECALL E0Z - REMEDY NOTICE - CERTAIN 2014 MODEL YEAR TUNDRA DOUBLE AND CREWMAX VEHICLES - CURTAIN SHIELD AIRBAG Status: Remedy Available
				Locate an authorized Toyota dealer near you to schedule an appointment  Learn more about this recall

Description: The subject vehicles are equipped with side Curtain-Shield-Airbags (CSA) which deploy from the roof rails in the event of certain types of collisions. Due to a possible mis-installation of a garnish on the center roof pillars, the garnish could interfere with a CSA and not allow it to achieve its intended inflation shape.

In some situations, this could increase the risk of injury to an occupant in the event of a crash.

Remedy: Toyota dealers will inspect the garnishes. If a garnish is found to be mis-installed, it will be replaced. The inspection and remedy procedure will be performed at No Charge to the vehicle's owner.

06/29/2015	45,597	Valvoline Instant Oil Change Flagstaff, AZ 928-556-0400 vioc.com	Oil and filter changed
04/07/2016		Toyota Motor Sales, USA, Inc.	<p>Manufacturer Service Campaign issued Campaign #F0A SPECIAL SERVICE CAMPAIGN (SSC) F0A - CERTAIN 2012 - 2014 MODEL YEAR TUNDRA AND SEQUOIA VEHICLES - ECM SOFTWARE UPDATE Status: Remedy Available</p> <p>Locate an authorized Toyota dealer near you to schedule an appointment</p> <p>- Learn more about this campaign</p>
<p>Description: In certain 2012 - 2014 Model Year Toyota Tundra and Sequoia vehicles equipped with a 5.7 Liter gasoline or 5.7 Liter-Flex Fuel engines, the Engine Control Module (ECM) may set a Diagnostic Trouble Code (DTC) if debris/ice becomes lodged in the air switching valve. If this occurs, the Malfunction Indicator (Check Engine) Light could illuminate and the vehicle could enter a "Fail-Safe" Mode (also known as "Limp-Home" Mode). If this occurs the vehicle's power and speed will be reduced, which could inconvenience you and require immediate repair. Toyota has developed new Engine Control software logic to help prevent this condition from occurring.</p> <p>Remedy: Authorized Toyota dealerships are requested to perform a software update at NO CHARGE to the vehicle's owner.</p>			
12/06/2017	104,495	Pep Boys Flagstaff, AZ 928-526-0556 pepboys.com	Maintenance inspection completed Tire(s) replaced Tire pressure monitoring system serviced
05/10/2018	112,336	Pep Boys Flagstaff, AZ 928-526-0556 pepboys.com	Maintenance inspection completed
11/06/2018	117,648	Dealer Inventory	Vehicle offered for sale
11/08/2018		Planet Chrysler Dodge Jeep Flagstaff, AZ 928-774-5337 driveplanet.com	Oil and filter changed Front brake rotor(s) replaced Front brakes replaced Brake rotor(s) replaced Tire(s) balanced Tires rotated Safety inspection performed Vehicle washed/detailed
12/31/2018	117,649	Planet Chrysler Dodge Jeep Flagstaff, AZ 928-774-5337 driveplanet.com	Vehicle serviced