



# History-Based Value Report

## History events affecting this vehicle's value



No Accidents Reported



1-Owner Vehicle



Service History

**\$24,170 Retail Value**



## CARFAX® Vehicle History Report™

US \$39.99

An independent company established in 1986

### Vehicle Information:

**2014 FORD F350 SUPER DUTY**  
VIN: 1FT7X3BT6EEB52555  
4 DOOR EXTENDED CAB PICKUP  
6.7L V8 F OHV 32V  
DIESEL  
REAR WHEEL DRIVE W/ 4X4  
[Standard Equipment](#) | [Safety Options](#)

### CARFAX Report Provided By:

Wheel Kinetics, LLC  
1909 W Gardner Ln  
Tucson, AZ 85705  
(800) 860-0194  
[www.wheelkinetics.com](http://www.wheelkinetics.com)



No accidents reported to CARFAX



No damage reported to CARFAX



CARFAX 1-Owner vehicle



**37** Service history records



Commercial vehicle



**161,747** Last reported odometer reading



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 2/4/19 at 11:46:00 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



## Ownership History

The number of owners is estimated

Owner 1

Year purchased

2014

Type of owner

Commercial

Estimated length of ownership

4 yrs. 8 mo.

Owned in the following states/provinces

Texas

Estimated miles driven per year

36,420/yr

Last reported odometer reading

161,747



## Title History

<a href="#">Salvage</a>   <a href="#">Junk</a>   <a href="#">Rebuilt</a>   <a href="#">Fire</a>   <a href="#">Flood</a>   <a href="#">Hail</a>   <a href="#">Lemon</a>	<b>Guaranteed</b> No Problem
<a href="#">Not Actual Mileage</a>   <a href="#">Exceeds Mechanical Limits</a>	<b>Guaranteed</b> No Problem



**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [Register](#) | [View Terms](#) | [View Certificate](#)

<b>Additional History</b>		Owner 1
Not all accidents / issues are reported to CARFAX		
<b>Total Loss</b> No total loss reported to CARFAX.		No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.		No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.		No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.		No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.		No Issues Reported
<b>Manufacturer Recall</b> A current list of recalls is available at <a href="#">Ford Motor Company</a> .		No Recalls Reported
<b>Basic Warranty</b> <a href="#">Original warranty</a> estimated to have expired.		<b>Warranty Expired</b>

**Detailed History** [Glossary](#)

<b>Owner 1</b>		<b>Date:</b>	<b>Mileage:</b>	<b>Source:</b>	<b>Comments:</b>
Purchased:	2014	02/01/2014		NICB	Vehicle manufactured and shipped to original dealer
Type:	Commercial				
Where:	Texas				
Est. miles/year:	36,420/yr	02/21/2014		Five Star Ford of Plano Plano, TX 972-985-3600 fivestarfordofplano.com/	Vehicle offered for sale
Est. length owned:	5/30/14 - present (4 yrs. 8 mo.)				
		03/04/2014	5	Five Star Ford of Plano Plano, TX 972-985-3600 fivestarfordofplano.com/	Pre-delivery inspection completed Vehicle washed/detailed Safety inspection performed Emissions or safety inspection performed
		05/30/2014	12	Texas Motor Vehicle Dept. Midland, TX Title #16530941778113416	Title issued or updated First owner reported Titled or registered as commercial vehicle Vehicle color noted as White
		06/20/2014	7,169	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed
		09/04/2014	14,632	Lube N Go El Paso, TX	Maintenance inspection completed Oil and filter changed

		915-591-5998 lubengoautocare.com	
12/30/2014	26,856	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed Air filter replaced Air filter checked
03/09/2015	32,433	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed
05/01/2015		Texas Motor Vehicle Dept. Midland, TX Title #16530941778113416	Registration issued or renewed Passed safety inspection Vehicle color noted as White
05/04/2015	37,664	Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com	Oil and filter changed Tires rotated
11/23/2015	56,983	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed Oil pan drain plug replaced
01/14/2016		Ford Motor Company	Manufacturer Customer Satisfaction Program issued Program #15M02 EXHAUST GAS TEMPERATURE SENSOR EXTENDED COVERAGE  Locate an authorized <a href="#">Ford or Lincoln Mercury dealer</a> or call 866-436-7332 to obtain more information
02/10/2016	63,212	Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com	Fuel filter replaced
03/17/2016	66,763	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed
05/01/2016		Texas Motor Vehicle Dept. Midland, TX Title #16530941778113416	Registration issued or renewed Passed safety inspection Vehicle color noted as White
06/14/2016	74,146	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed
08/10/2016	79,984	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed
09/15/2016		Service Facility Midland, TX	Oil and filter changed Tire(s) replaced Tire valve stem(s)/core(s) replaced Tire condition and pressure checked
12/01/2016	90,245	Service Facility Midland, TX	Oil and filter changed Tires rotated Wiper(s) replaced Air filter replaced
01/31/2017	96,435	Service Facility Midland, TX	Tire valve stem(s)/core(s) replaced Tire(s) replaced Oil and filter changed
02/28/2017	99,250	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Safety inspection performed

04/03/2017	102,784	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed Fuel filter replaced Water separator replaced
04/06/2017	103,534	Service Facility Midland, TX	Tire(s) replaced Tire valve stem(s)/core(s) replaced
05/01/2017		Texas Motor Vehicle Dept. Des Plaines, IL Title #16530941778113416	Registration issued or renewed Passed safety inspection Vehicle color noted as White
06/12/2017	108,907	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed Air filter replaced Air filter checked
06/28/2017	110,346	Service Facility Midland, TX	Tires rotated Oil and filter changed Air filter replaced Air filter checked
08/04/2017	114,693	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Air filter replaced Oil and filter changed Air filter checked
08/17/2017	114,745	Service Facility Midland, TX	Tires rotated Battery/charging system checked Tire valve stem(s)/core(s) replaced Tire(s) replaced Oil and filter changed Air filter replaced Air filter checked
10/04/2017	119,826	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed
11/24/2017		Service Facility Midland, TX	Oil and filter changed Tire repaired Tires rotated
12/04/2017	125,195	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Air filter replaced Oil and filter changed Air filter checked
12/11/2017		Ford Motor Company	Manufacturer Customer Satisfaction Program issued Program #17M04 CRANKCASE VENTILATION OIL SEPARATOR ASSEMBLY  Locate an authorized <a href="#">Ford or Lincoln Mercury dealer</a> or call 866-436-7332 to obtain more information
01/02/2018		Service Facility El Paso, TX	Recommended maintenance performed Oil and filter changed Air filter replaced Air filter checked Tire(s) replaced Rear shock absorber(s) replaced Front shock absorber(s) replaced Exhaust system checked Exhaust fluid serviced Thrust angle alignment performed Tire valve stem(s)/core(s) replaced Front brake rotor(s) replaced Rear brake rotor(s) replaced Serpentine belt replaced Antifreeze/coolant flushed/changed Fuel filter replaced Fuel system checked
01/19/2018	128,730	Shamaley Ford	Maintenance inspection completed

		El Paso, TX 915-591-8600 shamaleyford.com/	Rear brake pads replaced Brake rotor(s) resurfaced Four wheel alignment performed Oil and filter changed Fuel filter replaced Front brake pads replaced Antifreeze/coolant flushed/changed Drivability/performance checked Steering/suspension checked One tire mounted One tire balanced Four tires balanced Four tires mounted Rear suspension checked
02/22/2018	133,352	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Maintenance inspection completed Oil and filter changed Air filter replaced Air filter checked
02/22/2018	133,360	Martin Tire Company El Paso, TX 915-592-6496 martintire.com	Vehicle serviced
03/05/2018	134,616	Lube N Go El Paso, TX 915-591-5998 lubengoautocare.com	Safety inspection performed
04/10/2018		Service Facility El Paso, TX	Oil and filter changed Air filter replaced Air filter checked
04/25/2018	139,793	Martin Tire Company El Paso, TX 915-592-6496 martintire.com	Tire repaired
05/01/2018		Texas Motor Vehicle Dept. Sparks Glencoe, MD Title #16530941778113416	Registration issued or renewed Passed safety inspection Vehicle color noted as White
05/30/2018	144,450	Martin Tire Company El Paso, TX 915-592-6496 martintire.com	Tires rotated Oil and filter changed Air filter replaced Air filter checked
07/11/2018	149,639	Martin Tire Company El Paso, TX 915-592-6496 martintire.com	Oil and filter changed Tires rotated
08/15/2018	154,679	Martin Tire Company El Paso, TX 915-592-6496 martintire.com	Tires rotated Oil and filter changed Oil pan drain plug replaced
10/11/2018	158,342	Casa Ford Lincoln El Paso, TX 915-779-2272 casaford.com	Front brakes replaced Brake rotor(s) resurfaced Brakes checked Front brake rotor(s) resurfaced Front brake pads replaced Fuel filter replaced Fuel system cleaned/serviced Air filter replaced Air filter checked Exhaust system checked
10/18/2018	160,385	Martin Tire Company El Paso, TX 915-592-6496 martintire.com	Tires rotated
11/06/2018	161,747	Service Facility El Paso, TX	Brake light bulb(s) replaced